

# T = 5 L A

## POWERWALL

CERTIFIED INSTALLER

# Powerwall Job Check Out



### Job Check Out

The **Job Check Out** (JCO) should be submitted after completion of a Powerwall installation

The JCO enables Tesla to have visual records of installations and will provide valuable insight when trying to troubleshoot sites remotely

The report will help us provide a better service to you and your customers and assist with our Quality management

The form has been made as short as possible

Each Month an award will be given for the Number of submissions.





### Start: Basic info


#### Step 1

Scan QR code or go to: https://cutt.ly/TeslaUK



#### Step 2

Fill in "Your Details"






## Step 3: Cabling details

#### Enter details regarding:

- AC cable
- The communication & power cables between Powerwall and Gateway








## Step 4: photos

Photos can be taken on the phone or uploaded, make sure to get clear well lit photos






#### **Circuit Protection**

Take a photo of any associated electrical equipment for the Powerwall. I.e. Fuse boards, Isolators



**Gateway Wiring** 

Take a photo of the internals of your finished gateway.




SLD and Test Cert

Take a photos of the single line diagram and test cert.

This is almost the most important photo



## More photos





#### **Powerwall Wiring**

Powerwall AC wiring chamber, and any other photos you think could help.





#### **Overview Photo**

Take a photo capturing as much of the installation as possible. Show off your excellent install!




Additional

Take a photos of anything you think is relevant or special.

Show why you are No1!



## Finally



Tell us anything you would like to share (ideas or issues you experienced)

Hit the "Submit" button